




1461AM AIR CONTROL VALVE REBUILD


SERVICE PARTS LIST



Parts are not available individually.

Note: White Teflon or Lithium type grease should be used on all O-Rings before assembly.

Only new style valves can be serviced with these repair kits built after May 1989 (Build codes 27866, 27879 and later). Valves using a Shrader valve design (Tire valve stem) cannot be serviced.



PARTS LIST AND DESCRIPTION

RBK-1461AM REBUILD KIT		
ITEM	QTY	DESCRIPTION
1	1	Cam
2	1	Detent Sleeve
3	1	O-Ring – Cam
4	4	O-Ring – Piston
5	1	Piston (Lower)
6	1	Piston (Raise)
7	1	O-Ring – Exhaust Seat
8	1	O-Ring – Seat Retainer
9	1	O-Ring – Screw
10	1	O-Ring – Manifold

GSK-1461AM MINOR PISTON/SEAL KIT		
ITEM	QTY	DESCRIPTION
3	1	O-Ring – Cam
4	4	O-Ring – Piston
5	1	Piston (Lower)
7	1	O-Ring – Exhaust Seat
8	1	O-Ring – Seat Retainer
9	1	O-Ring – Screw
10	1	O-Ring – Manifold

1462A STEEL SHANK HANDLE KIT		
ITEM	QTY	DESCRIPTION
11	1	Knob, Shank & Spring Assembly